
Step 1. Assemble column.



Step 4. Attach wings to column.



Steps 2&3. Insert puck lights in canopy plex.
Place canopy on column, tighten column top CBX clamp using Red/Black handle 5mm hex wrench.

